







Instructions for Assembling Keyboard Desk

Included Parts with the Keyboard Desk - BOX 3


	Keyboard Desk Main Surface	x1
	Keyboard Desk Leg - Left	x1
	Keyboard Desk Leg - Right	x1
	Keyboard Spreader Bar Assembly	x1
	Work Surface Stiffener	x1
	#8 x .75" Pan Head Wood Screw	x50
	Work Surface Bracket	x4
	Leg Leveler Assembly	x4

ULTIMATE SUPPORT®




Lay the left keyboard desk leg down with the holes facing up.


Screw on two work surface brackets. Then screw on leg leveler assembly. Repeat on right keyboard desk leg.



Lay keyboard desk main surface down with holes and grooves facing up. Place work surface stiffener into keyboard desk main surface center groove. Use ten screws to attach.



Attach left leg to main desk surface using six provided screws. Repeat on right leg.



Stand up keyboard desk. Place spreader bar in between both legs. Attach bar with four screw on both sides.